

Certificate of Compliance

Certificate Number **20081125-E72861H**
Report Reference **E72861, 1991 January 30**
Issue Date **2008 November 25**

Page 1 of 2



Issued to: **BREMAS ERSCE SPA**

VIA MILANO 26
20060 LISCATE MI ITALY

*This is to certify that
representative samples of*


AUXILIARY DEVICES
See Addendum for Models.

*Have been investigated by Underwriters Laboratories Inc.® in
accordance with the Standard(s) indicated on this Certificate.*

Standard(s) for Safety: **UL 508 - Industrial Control Equipment
CSA-C22.2 No. 14 - Industrial Control Equipment**

Additional Information: **See Report for Ratings.**

Only those products bearing the UL Listing Mark for the US and Canada should be considered as being covered by UL's Listing and Follow-Up Service meeting the appropriate requirements for US and Canada.

The UL Listing Mark for the US and Canada generally includes: the UL in a circle symbol with "C" and "US" identifiers:  the word "LISTED"; a control number (may be alphanumeric) assigned by UL; and the product category name (product identifier) as indicated in the appropriate UL Directory.

Look for the UL Listing Mark on the product

Issued by:
Matteo Redaelli, Engineering Services
Underwriters Laboratories Inc.

Reviewed by:
Tim Lueck, Engineering Services
Underwriters Laboratories Inc.

Certificate of Compliance

Certificate Number **20081125-E72861H**
Report Reference **E72861, 1991 January 30**
Issue Date **2008 November 25**

Page 2 of 2



This is to verify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

MODELS

Series E10, E20 followed by 0, 1 or 2, followed by 00, 01, 02, 03, 04, 05, 06, 07, 10, 40 or 40S, followed by various characters, followed by M, I or P and maybe followed by other characters.

Series E30 followed by 0, 1 or 2, followed by 00, 01, 02, 03, 04, 05, 06, 07, 10, 40 or 40S, followed by various characters, followed by M and maybe followed by other characters.

Series E40 followed by 0, 1 or 2, followed by 00, 01, 02, 03, 04, 05, 06, 07, 10, 40, 40S, 80 or 81 followed by various characters, followed by M, I or P and maybe followed by other characters.

Issued by:
Matteo Redaelli, Engineering Services
Underwriters Laboratories Inc.

Reviewed by:
Tim Lueck, Engineering Services
Underwriters Laboratories Inc.